MBUSI Service Parts

Supplier Guide

Quality of Parts / PPAP Requirements

Document History

Version Number	Author	Location of Change(s)	Summary of Changes	Date
Version 1	FATORRE		Final Draft Version	5/1/2022

PPAP Requirements

Introduction:

This document will give suppliers an understanding of the Global Service Parts, (MBUSI GSP) PPAP Submission process, in order to successfully meet initial part approval. Service Parts SQE adhere to the requirements of the VDA 2 QUALITY ASSURANCE FOR SUPPLIERS – Production Process and Product Approval Standard. Because this VDA Standard is an automotive industry standard practice, it is mandatory that all Service Parts Suppliers adhere to this standard also.

Contact Information:

For any quality-related questions, please refer to the Quality Manager in the MBUSI Contacts tab within the Service Parts Supplier Portal.

Content:

Suppliers are required to follow the PPAP requirements listed in the VDA 2 – Quality Assurance for Supplies – PPA (it is the suppliers responsibility to have the necessary VDA documents available).

- 1. All service parts that are current series parts can default to PPAP submissions to the PIA. Please reference the applicable PIA Information/PE # when required.
- 2. All service parts that are service unique can be of the PIA submission **UNTIL** a change (i.e. location change, process change, etc.) occurs.
- 3. When a change (any event which requires a new PPAP) occurs the supplier and the Service Part SQE will agree upon the level of PPAP submission required (refer to step 3 in the VDA PPAP Cover Sheet Instructions link).
- 4. Reference the below attachment for details regarding the proper method for filling out the VDA Cover Sheet.
 - NOTE: This document is a requirement for ALL submission regardless of the agreed upon Level as mentioned in step 3. This document is reference, if the supplier has other preferences for a compatible form, the Service Parts SQE must agree with the proposed form.
- 5. The VDA 2 Standard is the default reference document for all questions related to Service Part PPAP processes.

Service Parts QC follows the requirements and recommendations of VDA 2 for the PPAP submission and part approval process. Below our instructions for the submission of the cover sheet and a link to download it can be found.



VDA2 PPAP Submission Requirements

ATTN SQE:	Supplier Name:			SUBMISSION TYPE:			SUBMISSION LEVEL:				
Customer Information: MBUSI SERVICE PARTS NACW 3588 Bibbville Rd. Woodstock, AL. 35188	Supplier Code: pplier Contact Info: Name: Phone: Email:		Report covering other samples								
Attachments / Items For Inspection											
Product / Process											
1.1 Geometry, dimer 1.2 Function check 1.3 Material check 1.4 Haptic check 1.5 Acoustics check 1.5 Odour check 1.7 Appearance che 1.8 Surface check		1.9 ESD test 1.10 Reliability te: 2 Samples 3 Technical specif 4 Product FMEA 5 Design release 6 Compliance with 7 Material data sh	cations	3 Proce Con	ocess are test report ss FMEA sess flow chart trol plan firmation of process capabilit ievement of special character j/inspection equipment list ability study testing equipmer	17 18 19 19 19 19 19 19 19 19 19 19 19 19 19	Tooling list Confirmation of agre Written self-assessm Part history Confirmation of suita PPA status of the su Approval of coating	ent ability of transport equipment pply chain			
				Part Inform	ation						
Part Description: Drawing Number: Issue / Date: SQMS / PE:		Part Numbers:	SUP	4 NF	RMATION:						
CONFIRMATION BY SUPP	OLIED It is horoby	Signee Information:			Comments:		Signature:				
confirmed that the sample s carried out in accordance submission level to V	submission has been with the agreed	Name: Phone: Email: Department:			The IMDS data set has beer drawn up under IMDS ID-No.		Date:				
Customer's Decision (To Be Filled Out By MBUSI SQE)											
OK Conditionally OK: Follow-U NOK: Re-approval of PPA P Deviation Approval Number: Name: Department:		OVERALL Overall Process	Overall 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	14 1.5 15 1.7	Approval Product / Produc	0		23 22 22 21 21 20 20 20 30 40 40 40 40 40 40 40 40 40 40 40 40 40			
	E SIGNATURE:					Date:					

1) Sender:

Enter Company Name and Address of supplier submitting this PPAP.

2) Identify the reason for the PPAP submission:

Use the first option First Sample Test Report VDA for all first time submissions, otherwise, use the applicable agreed upon selection.

3)

4) Highlight the applicable fields when any additional information is required for the PPAP submission.

Examples:

- a. Highlight 1.1 Geometry Dimensional Check for any dimensional data required and being submitted with this submission.
- b. b) Highlight 1.7 Appearances for any visual requirements required and being submitted with this submission.



Created on: 5/1/2022 Modified on: N/A

5) Supplier Details:

A signature from the responsible mgmt. representative of the supplier is required. Step 4 is very important step and must be filled in accurately and as complete as possible – any questions should be directed to your MBUSI Service Part SQE ASAP.

6) Customer Decision:

This will be filled out by the MBUSI Service Part SQE.

Please find the link to the VDA PPAP Cover Sheet in the Supplier Guide Quality folder, titled SG 4.1